


接线图 WIRING DIAGRAM

缩写目录：Abbreviated Directory:


TC: 恒温保护 Constant temperature protection	1~: 单相电机 Single-phase machine	Cr: 运行电容器 Running capacitor
BR: 制动器(可选) Brake (optional)	3~: 三相电机 Three-phase machine	Cs: 起动电容器 Start capacitor

电缆出线 Cable Outlet

单相电机带热保护控制7根引出线 Single Phase Motor With Thermal Protection Control Of 7 Lead Wire





单相电机带电磁制动带热保护器9根引出线 Single Phase Motor With Electromagnetic Brake With Heat Protector 9 Lead Wire





三相电机带热保护控制6根出线 Three Phase Motor With Thermal Protection Control Of 6 Wire





● 三相电机带电磁制动器带过热保护器8根出线
Three Phase Motor With Electromagnetic Brake With Over 8 Outlet





● 三相电机带过热保护器9根出线
Three Phase Motor With Over 9 Outlet



● 三相电机带电磁制动器带过热保护器11根出线
Three Phase Motor With Electromagnetic Brake With Over 11 Outlet



● 三相电机带电磁制动器11根出线
Three Phase Motor With Electromagnetic Brake 11 Outlet



注Notes:

三角形连接: 低电压
Triangular connection: low voltage

P星形连接: 高电压
P star connection: high voltage

P双星形: 低电压
P binary form: low voltage

接线图 WIRING DIAGRAM

缩写目录：Abbreviated Directory:



TC: 恒温保护 Constant temperature protection
BR: 制动器(可选) Brake (optional)

1~: 单相电机 Single-phase machine
3~: 三相电机 Three-phase machine



Cr: 运行电容器 Running capacitor
Cs: 起动电容器 Start capacitor

接线盒出线 Junction Box



单相电机带过热保护器7根引线 Single Phase Motor With Over 7 Lead Wire



单相电机带电磁制动器和过热保护器9根引线 Single Phase Motor With Electromagnetic Brake And Overheat Protector 9 Lead Wire





三相电机带过热保护器6根引线 Three Phase Motor With Over 6 Lead Wire





● 三相电机带电磁制动器带过热保护器8根引线

Three Phase Motor With Electromagnetic Brake With Over 8 Lead Wire





● 三相电机带过热保护器9根引线

Three Phase Motor With Over 9 Lead Wire





● 三相电机带电磁制动器带过热保护器11根引线

Three Phase Motor With Electromagnetic Brake With Over 11 Lead Wire



● 三相电机带过热保护器12根引线

Three Phase Motor With Over 12 Lead Wire



注Notes:

三角形连接: 低电压
Triangular connection: low voltage

P星形连接: 高电压
P star connection: high voltage

P双星形: 低电压
P binary form: low voltage